


Plutonium IN THE UNITED STATES



© WISE- Paris

104 OPERATING NUCLEAR POWER PLANTS

- 69 Pressurized Water Reactors (PWR)
- 35 Boiling Water Reactors (BWR)

NO CURRENT REPROCESSING PLANT

2 SITES OF PLUTONIUM HANDLING

- Lawrence Livermore Laboratory
- Rocky Flats

2 STORAGE SITES FOR LOW AND MEDIUM LEVEL RADIOACTIVE WASTE

- WIPP: Waste Isolation Pilot Plant
- Barnwell (South Carolina)

6 DOE INTERIM STORAGE SITES FOR LOW, MEDIUM AND HIGH LEVEL RADIOACTIVE WASTE

- Savannah Rive
- Los Alamos
- Hanford
- Pantex
- Oak Ridge
- Idaho Falls